

LSB or USB Mode

Slow AGC

Power Tx Meter

CH1 Quick Memory

Off Tx EQ

Off Rx EQ

use LSB for 80 & 40m, USB for 20, 15 & 10m

use slow for SSB and fast for CW

100 % RF Gain

100 W RF Power

0.1 KHz DSP Low Cut-Off

3.4 KHz DSP High Cut-Off

2 KHz CW Filter Width

1.3 KHz FC Shift

6 NR Level

TX Proc A / B

A=B Split CW-T

Pre ATT NB

BC1 BC2 DNL1

DNL2 DNL3 NR1

NR2 Stop